## LIST OF FIGURES AND TABLES

Figure	
1-1	Program Manager's Reporting Chain
1-2	Acquisition Management Structure
2-1	Productivity Results from Effective Interaction of the Work Force, the Processes, and the Product
2-2	Industrial Spending in U.S. for Research and Development
2-3	Air Force Data Flow for Production Base Analysis
2-4	Graduated Mobilization Response
3-1	The Generic Product Development Process
3-2	Manufacturing Management for Major DOD Acquisition Programs
3-3	Contracting Support
4-1	Systems Acquisition Strategic Environment
4-2	Manufacturing Constraints and Risks
4-3	Elements of Manufacturing Strategy
4-4	Manufacturing Strategy Decisions
4-5	Critical Design Disciplines
4-6	General Leader/Follower Contracting Objectives
4-7	Leader/Follower Conditions for Use
4-8	Multi-Year Contracting Objectives
4-9	Multi-Year Contracting Criteria
5-1	The Fourteen Management Principles of Dr. Deming
5-2	DOD Posture on Quality
5-3	Examples of Pareto Chart Before and After Improvement
5-4	Sample of Ishikawa Diagram

<u>Figure</u>	
5-5	Off-line and On-line Quality Control Via Taguchi
5-6	Objectives of DOD Quality Programs
5-7	DOD Quality Concept
5-8	Potential Savings
5-9	Major Objectives of DOD Reliability & Maintainability Policy
5-10	Typical Tests Yielding Reliability Information
5-11	Assessment of Reliability Growth
5-12	Reliability Growth Curve
5-13	Reliability and Maintainability Quality Team Model
5-14	Concurrent Engineering Approach vs. Typical Approach
6-1	Manufacturing Resources
6-2	Manufacturing Risk Assessment
6-3	Extract from Manufacturing Plan
6-4	Master-Phasing Chart for a Typical Defense System Production Program (Simplified)
6-5	Example of First Unit Flow Chart for a Symbol Generation
6-6	Master Schedule for an Electronics LRU
6-7	Hierarchy of Schedules
6-8	Typical Hierarchy of Schedules
6-9	Proposed Steps in a JIT Manufacturing Program
6-10	Lead Times
6-11	Actions to Minimize Impact of Lead Time Variations
6-12	Materials Requirements Planning Information Flow
6-13	Manufacturing Resources Planning II Information Flow
7-1	Physical Characteristics
7-2	Producibility Considerations During the Interative Design Process

<u>Figure</u>	
7-3	Engineering Design Criteria
7-4	Planning Data Requirements
7-5	Producibility Engineering Planning Objectives
7-6	Producibility Engineering Planning Funding Profile
7-7	Producibility Analysis Checklist
8-1	Manufacturing Processes Available for Metal Fabrication
8-2	Relative Machining Costs and Surface Finish
8-3	Symptoms of Poor Facility Layout
8-4	Future Trends in Technology
8-5	Manufacturing Technology/Acquisition Management
8-6	Cost Reduction Example
8-7	IMIP and Program Baseline Adjustments
8-8	Typical Robot Tasks
8-9	Typical Manufacturing Cost Distribution
8-10	Comparison of Manufacturing Method Unit Costs, By Level of Production
8-11	Interrelationships of Discrete Design Phases
8-12	CAD/CAM - How It Works
8-13	Integrated Manufacturing System
9-1	Manufacturing Costs Genesis
9-2	Manufacturing Improvement Curve
9-3	Components of Learning
9-4	An 80 Percent Learning Curve Drawn on Arithmetic Graph Paper
9-5	An S-Curve Model
9-6	Learning Curve
9-7	Manufacturing Rate Options

Figure	
10-1	Manufacturing Management Program Goals
10-2	MIL-STD-1528A Requirements
10-3	Incentive Improvement Goals
10-4	Contractor Make-or-Buy Program Support
10-5	Contractor Purchasing System Review Special Concerns
10-6	Contract Data Requirements List Data Objectives
10-7	Typical Manufacturing Management Data Items
10-8	Uses of Technical Data
11-1	Acquisition Process for Major Weapon Systems
11-2	Critical Path Templates
11-3	Template Timelines
11-4	PRR Template Relationship
11-5	Production Planning - Template Relationship
12-1	Product-Centered Surveys
12-2	Design Reviews
12-3	Production Readiness Indicators
12-4	Projected Profile for Engineering Change Traffic
12-5	Projected Profile for Test/Process Yields
12-6	Projected Profile for Requirements Changes, Error Discovery, and Coding Revisions
12-7	Product Design Evaluation Issues
12-8	Contract Administration Office Expertise
13-1	Typical Manufacturing Problem Areas
13-2	Configuration Management by Baselines
13-3	Benefits of Work Measurement Systems
13-4	Flements of a Contractor's Work Measurement System

<u>Figure</u>	
13-5	Work Breakdown Structure Level Identification
13-6	Work Breakdown Structure Extended to Cost Account and Work Package Level
13-7	Objective Chart
13-8	Production Plan
13-9	Line-of-Balance Chart
14-1	Integrated Manufacturing System
14-2	Open Systems Interconnection Model
14-3	Concurrent Engineering Model
14-4	System Integration in Concurrent Engineering
14-5	CALS Management Organization
14-6	Transitional Plan for the IWSDB
14-7	Integrated Weapon System Data Base
14-8	Current Data Transfer
14-9	Near Term Improvements
14-10	Computer-Aided Logistics Support
<u>Table</u>	
6-1	Estimated Percent Improvement for Different Industries as Result of JIT Implementation
9-1	Factors Leading to Manufacturing Improvement
9-2	Cost Impact of Varying Baseline Unit for Standard